
TITLE: TURBINE NOZZLE SEGMENT AND METHOD OF REPAIRING SAME INVENTOR: JOHN HEYWARD, et al. DOCKET: 13DV-13961

ATTY.: JONATHAN HINES; PHONE: (207) 791-1236




The state of the s


TITLE: TURBINE NOZZLE SEGMENT AND METHOD OF REPAIRING SAME INVENTOR: JOHN HEYWARD, et al.

DOCKET: 13DV-13961 ATTY.: JONATHAN HINES; PHONE: (207) 791-1236









100 ļ. į. 

TITLE: TURBINE NOZZLE SEGMENT AND METHOD OF REPAIRING SAME INVENTOR: JOHN HEYWARD, et al. DOCKET: 13DV-13961

ATTY.: JONATHAN HINES; PHONE: (207) 791-1236

